# USB Fiber Operation Guide

Product Information Page

Setup Summary

(1) Plug fiber cable into both transceivers
(2) Plug USB transceivers into USB ports
(3) Let FTDI driver install
(4) Use 'PuTTY' to test
(5) Set to 9600 baud, 8 N 1
(6) Type 'Hello World' into terminal
(7) Observe 'Hello World' on the receiver terminal

Specifications

- Win / Mac / Linux
- USB A
- UART (TTL)
- >1 Mbps
- >30 m
- <100 mA